

STATE OF TEXAS

Board of Water Engineers

AREAS WITH DEFICIENT AND SURPLUS RAINFALL IN 1953

Bulletin 5914 | Plate X