

Figure 44. Fluoride Content of Water From Seymour Aquifer, 1975–1977