

Figure 39. Chloride Content of Water From Seymour Aquifer, 1975–1977