

EXPLANATION

- • LOCATION OF WELL USED FOR CONTROL
- 475 / 24 — DEPTH TO TOP OF CARRIZO SAND, FEET / ALTITUDE OF TOP OF CARRIZO SAND, FEET ABOVE OR BELOW (-) MEAN SEA LEVEL
- e — INDICATES ESTIMATED DATA
- —200— CONTOUR SHOWING APPROXIMATE ALTITUDE OF TOP OF CARRIZO SAND, FEET ABOVE OR BELOW (-) MEAN SEA LEVEL. CONTOUR INTERVAL - 100 FEET
- PRINCIPAL OUTCROP OF CARRIZO SAND, CONTACTS DOTTED WHERE CONCEALED
- U/D — FAULT, U-UPTHROWN SIDE, D-DOWNTHROWN SIDE

NOTE: OUTCROP OF CARRIZO SAND AND FAULTS FROM GEOLOGIC ATLAS OF TEXAS, DALLAS, TYLER, AND WACO SHEETS, BUREAU OF ECONOMIC GEOLOGY, UNIVERSITY OF TEXAS, VARIOUS DATES.

Figure 49

Depth and Altitude of Top of Carrizo Sand in Henderson County

Base from Texas State Highway Department county map

C2