

Figure 26

Pumpage Patterns for Optimizing Development of Ground Water From the Carrizo Aquifer, 1970-2020