(18)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Water Resources Branch 15in840

Water Level Measurements _____ Field No. 15
Owner A. C. Hays Office No. 15
Tenant _____ County Parmer
Location NW-SW-Sec. 20- T-1-N-R-5 Type of well _____
Measuring Point top concrete base
Height of Meas. Point above land-surface datum 1.00'

Date	Depth to water below meas. point	Ht. M.P. above L.S.D.	Depth to water below L.S.D.	Meas. by	Remarks (pumping, M.P. changed, etc.)
6-23-37	140.13	1.00	139.13	CRF	Unused
8-15-37	140.10	1.00	139.10	JL	do.
10-26-37	140.00	1.00	139.00	LB	do.
1-12-38	139.91	1.00	138.91	CRF	do.
6-10-38	139.99	1.00	138.99	JWL	do.
9-15-38	139.90	1.00	138.90	JWL	do.
3-30-39	139.72	1.00	138.72	JWL	do.
9-14-39	139.81	1.00	138.81	WLB	do.
2-5-42	139.52	1.00	138.52	WHA	do.
8-3-42	139.39	1.00	138.39	WHA	do.
2-7-43	139.30	1.00	138.30	WHA	do.
2-18-44	139.22	1.00	138.22	JWL	do.
3-27-47	139.54	1.00	138.54	PBK	do.
3-17-48	139.55	1.00	138.55	BAS	do. W. well N.P.
3-17-49	140.05	1.00	139.05	ERL	do do.
2-14-50	141.88	1.0	140.88	F	do.
1-21-51	142.15	1.0	141.15	GJS	—
2-6-52	143.59	—	142.59	ERL	—
	107.30				
1-5-54	Well drilled deeper and new csg put inside pump sets on top of csg. no opening for [illegible] well is in small white [illegible] D.S. well				

(18) x Logan
On U.S. 60

9-185—July 1935
Revised

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
WATER RESOURCES BRANCH

duplicate

WELL SCHEDULE

Date June 23, 1937 Field No. 612
Record by C R Fallett Office No. 15
Source of data Clyde Hays

1. *Location:* State Texas County Parmer
Map 1 mi SE of Black
NW ¼ SW ¼ sec. 20 T 1 N R 5 E
2. *Owner:* A. C. Hays Address Friona
Tenant do Address do
Driller _____ Address _____
3. *Topography* Flat
4. *Elevation* _____ ft. above/below _____
5. *Type:* Dug, drilled, driven, bored, jetted about 1910
6. *Depth:* Rept. 200 ft. Meas. 166-1=165 ft.
7. *Casing:* Diam. 9 in., to _____ in., Type S
Depth _____ ft., Finish _____
8. *Chief Aquifer* _____ From _____ ft. to _____ ft.
Others _____
9. *Water level* 140.13 ft. rept./meas. June 23 1937 above/below top of concrete base which is 1 ft. above/below surface
10. *Pump:* Type _____ Capacity _____ G. M. _____
Power: Kind none Horsepower _____
11. *Yield:* Flow _____ G. M., Pump _____ G. M., Meas., Rept. Est. _____
Drawdown _____ ft. after _____ hours pumping _____ G. M.
12. *Use:* Dom., Stock, PS., RR., Ind. Irr. Obs. Not in use
Adequacy, permanence _____
13. *Quality* _____ Temp _____ °F.
Taste, odor, color _____ Sample Yes/No _____
Unfit for _____
14. *Remarks:* (Log, Analyses, etc.) _____

Drilled for irr. and used some CRF

UR 10-20-411

065 well

Water Level

6-23-37 — 140.13 CRF [illegible]
8-18-37 — 140.1 SWL. [illegible]
10-26-37 — 140.00 LB. ~~Not~~ [illegible]
1-12-38 — 139.91 CRF Not [illegible]

Well back of white building about 100 ft south of ½ line and 200 ft. East of road



#15-a

1-6-55 155.15 1.5 153.65 EFL. Mo

well west of old well. Layne Bowler, Bada Industrial engine. MP= log hole [illegible] pump on south [illegible] is 0.5 mi. North of SWC of section of SW¼ of NW¼

1-12-56 Owner [illegible]

UR 10-20-411